

WORLD-CLASS OUTSTANDING INTERNATIONAL
PROGRAM | EXHIBITION | NETWORKING

BOILER FEED WATER PUMPS PERFORMANCE LOSS

AMR MOHAMED GAD- RASGAS

DR.NICHOLAS WHITE – RASGAS

29TH INTERNATIONAL PUMP USERS SYMPOSIUM

HOUSTON SEPT.30TH -OCTOBER 3RD



42nd Turbomachinery
29th Pump SYMPOSIA



GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013

Presenter

Amr Mohamed Gad



- Senior Machinery Engineer with RasGas company since 2007
- 13 years of experience in maintenance, retrofits, and upgrades of Gas Turbines, Compressors and Pumps in natural gas facilities.
- Previous publications at 6 major worldwide conferences





Index

- RGX2 Steam Condensate System
- Problem Summary
- Troubleshooting History
- Unit 92-P261A –Failure
- Performance Deterioration
- RCFA-Unit 92-P261A
- Operational Risk Mitigation
- Recommendations Results
- Lessons Learned




RGX2 Steam Condensate System

Steam condensate system set up at RGX2:

- Total of x6 Boiler Feed Water Pumps (x4 steam turbine driven pumps and x2 motor driven pumps).

Operating philosophy N+2:

- x4 in service and x2 Stand by operation.






RGX2 Steam Condensate System

Pump specifications:

- Rated capacity 750 M3/hr
- Rated power 1.7 MW
- Differential head 680m
- Horizontally split casing
- 4 stage with double inlet impeller



RGX2 Steam Condensate System



New pump before installation



Old pump at skid in RGX2

Problem Summary

- One pump experienced high thrust bearing temperature alarm after 16 months of operation
- The thrust bearing was replaced twice during the following 6 months without identifying the root cause
- System operation indicated low pump performance
- During the 25 months of operation, thrust bearing temperature again reached high alarm level and pump was found seized upon inspection




Troubleshooting History

Historical Records:

Unit 92-P261A historical events shown on a timeline

pump's thrust bearing temperature increase due to bearing degradation over one year – alarm level reached (85 deg C)




Troubleshooting History

Unit 92-P261A -Vibration readings:

Pump D.E
radial vibration

Pump N.D.E
radial vibration


Turbine
D.E & N.D.E
radial vibration



Unit 92-P261A –Failure

Thrust Bearing failure signs:

Scored and smeared thrust pads



Smeared Journal pads




Unit 92-P261A –Failure



Casing erosion




Cavitations' damage





Unit 92-P261A –Failure


RCFA initiated August 2011 and completed Oct. 2011



Casing erosion




Performance Deterioration



Optimum performance ● Deteriorated performance ● Other pumps performance ●

RCFA-Unit 92-P261A



RCFA-Unit 92-P261A

RCFA – Findings:

- Root Cause (Human) - Incorrect material specification of the pump casing for boiler feed water service led to major damage of casing inner walls and rotor parts
- Contributing Factor 1 (Latent) – Insufficient online monitoring of pump performance due to inadequate instrumentation prevented effective pump health monitoring
- Contributing Factor 2 (Latent) – Inadequate surveillance program for boiler feed water conditions led to a possible corrosive environment within pump flow path






RCFA-Unit 92-P261A

RCFA – Recommendations:

- Immediate action: Purchase x6 new BFWPs with 12%Cr Stainless Steel casings (A487CA6NM) and replace the existing pumps with carbon steel casing (A216 WCB)
- Medium action: Revise Equipment Strategy to perform bi-monthly online performance monitoring task including steam condensate dissolved oxygen and PH levels to ensure remaining within specification
- Long term action: Improve online monitoring:
 - Digital discharge pressure transmitter
 - Install flow measurement devices on the discharge and recirculation line



Operational Risk Mitigation





Operational Risk Mitigation

Integrated Repair plan:


- x3 pumps repaired between Oct. 2011 and March 2012
- x2 pumps were repaired used spare parts supplied from third party as fast repair.
- System reviewed for equipment reliability (Turbines, Motors, Automatic Recycle Valves, Instruments etc.) and corrective actions taken as appropriate
- Frequent measurement of discharge and recycle flow using clamp flow meter to assess pump performance
- Long term - Installation of x6 new pumps with stainless steel casing (procurement and installation time-14 months)



Recommendations Results

- Performance for the repaired 3 units as interim solution was similar to OEM design.
- Ultimate replacement of all pumps by new stainless steel casing's units results in operating the BFW system with reliable units as per OEM design.

Optimum performance





Lessons Learned

- Follow API610 guidelines during procurement (material specifications versus fluid service)
- Improve datasheet and specification review during project FEED and procurement
- Improve online monitoring instruments required during plant design



Questions?

Authors:

Amr Mohamed Gad – RasGas


Dr. Nicholas White – RasGas

asmohamedgad@rasgas.com.qa



Backup





0	1	APPLICABLE TO:	<input type="radio"/> PROPOSALS	<input checked="" type="radio"/> PURCHASE	<input checked="" type="checkbox"/> AS BUILT			
0	2	FOR	Ras Laffan Liquefied Natural Gas Company Limited (3)			UNIT		
						92 Steam and Condensate System		
	3	SITE	RAS LAFFAN, QATAR			SERVICE		
						Boiler Feed Water Pump		
1	4	NO. REQ	5	PUMP SIZE	8x10x14.5 H/Y	TYPE		
						Centrifugal		
						NO. STAGES		
						4		
1	5	MANUFACTURER	UNION PUMP S.A.S.			MODEL		
						DVMX		
						SERIAL NO.		
						P350 to P354		
	6	NOTES: INFORMATION BELOW TO BE COMPLETED:	<input type="radio"/> BY PURCHASER			<input type="checkbox"/> BY MANUFACTURER		
			<input type="radio"/> GENERAL (3.1.1)			<input checked="" type="checkbox"/> BY MANUFACTURER OR PURCHASER		
0	8	PUMPS TO OPERATE IN (PARALLEL)	NO. MOTOR DRIVEN			2		
						NO. TURBINE DRIVEN		
						3 (2+1)		
1	9	GEARINGS WITH	92-P261A/B/C/D	PUMP ITEM NO.	92-P261C/D	PUMP ITEM NO.		
						92-P261A/B, 92-P271A		
1	10	GEAR ITEM NO.		MOTOR ITEM NO.	92-PM261C/D	TURBINE ITEM NO.		
						92-PT261A/B, 92-PT271A		
	11	GEAR PROVIDED BY		MOTOR PROVIDED BY	Pump Vendor	TURBINE PROVIDED BY		
						Pump Vendor		
	12	GEAR MOUNTED BY		MOTOR MOUNTED BY	Pump Vendor	TURBINE MOUNTED BY		
						Pump Vendor		
	13	GEAR DATA SHT. NO.		MOTOR DATA SHT. NO.		TURBINE DATA SHT. NO.		
	14	OPERATING CONDITIONS			SITE AND UTILITY DATA (CONT'D)			
E	15	CAPACITY, NORMAL	630.0 (m3/h)	RATED	750.0 (m3/h)	WATER SOURCE		
						Fresh Water		
	16	OTHER				CHLORIDE CONCENTRATION (PPM)		
						(3.5.2.6)		
E	17	SUCTION PRESSURE MAX./RATED	5.10 / 2.30 (BARG)			INSTRUMENT AIR: MAX/MIN PRESS		
						7 / 4.5 (BARG)		
0	18	DISCHARGE PRESSURE	65.20	*1.7 (BARG)		LIQUID		
0	19	DIFFERENTIAL PRESSURE	62.90	*1.7 (BAR)		TYPE OR NAME OF LIQUID		
0	20	DIFF. HEAD	*1.8	680.4 (m)	NPSHA	13.6 (m) *1.1	Boiler Feed Water *1.3	
E	21	PROCESS VARIATIONS					PUMPING TEMPERATURE:	
							NORMAL	
							120 (°C) MAX. 150 (°C) MIN. 43 (°C)	
	22	STARTING CONDITIONS	Auto Start/Stop *1.5 (3.1.3)				VAPOR PRESSURE	
							2 (BAR abs) @ 120 (°C)	
	23	SERVICE:	<input checked="" type="radio"/> CONT. <input type="radio"/> INTERMITTENT (STARTS/DAY)				RELATIVE DENSITY (SPECIFIC GRAVITY):	
							NORMAL	
							0.943 MAX. MIN.	
	24	PARALLEL OPERATION REQ'D (2.1.11)	*1.6				SPECIFIC HEAT, Cp	
							(kJ/kg °C)	
	25	SITE AND UTILITY DATA *1.2						VISCOSITY
							0.232 (cP) @ 120 (°C)	
	26	LOCATION: (2.1.29)					MAX. VISCOSITY	
			<input type="radio"/> INDOOR	<input type="radio"/> HEATED	<input type="radio"/> UNDER ROOF		(cP)	
	27		<input checked="" type="radio"/> OUTDOOR	<input checked="" type="radio"/> UNHEATED	<input type="radio"/> PARTIAL SIDES		CORROSIVE/EROSIVE AGENT	
							(2.11.1.8)	
	28		<input type="radio"/> GRADE	<input type="radio"/> MEZZANINE	<input type="radio"/>		CHLORIDE CONCENTRATION (PPM)	
							(3.5.2.6)	
	29		ELECTRIC AREA CLASSIFICATION (2.1.22 / 3.1.5)				H ₂ S CONCENTRATION (PPM)	
							(2.11.1.11)	
	30		*1.4				LIQUID (2.1.3)	
							<input type="radio"/> HAZARDOUS <input type="radio"/> FLAMMABLE	
	31		<input type="radio"/> WINTERIZATION REQ'D				<input type="radio"/> OTHER	
	32		<input checked="" type="radio"/> TROPICALIZATION REQ'D.				PERFORMANCE	
	33	SITE DATA (2.1.29)					PROPOASAL CURVE NO.	
							620319A/B/C/D	
0	34	ALTITUDE (m)	BAROMETER			1.013 (BAR abs)	RPM	
							2980	
0	35	RANGE OF AMBIENT TEMPS: MIN/MAX.	4 / 49 (°C)				IMPELLER DIA. RATED	
							368.45 MAX. 390 MIN. 351 (mm)	
0	36	RELATIVE HUMIDITY: MIN / MAX	35 / 80 (%)				RATED POWER	
							1673.2 (BHP) EFFICIENCY 79.2 (%)	
0	37	UNUSUAL CONDITIONS: (2.1.23)	<input checked="" type="radio"/> DUST <input type="radio"/> FUMES				MINIMUM CONTINUOUS FLOW:	
							THERMAL	
0	38	OTHER	Salty and dusty (Sand Storm)				(m3/h)	
							230 (m3/h)	
0	39	UTILITY CONDITIONS:					PREFERRED OPERATING REGION	
							535 TO 920 (m3/h)	
0	40	STEAM: DRIVERS	HEATING				ALLOWABLE OPERATING REGION	
							340 TO 950 (m3/h)	
0	41	MIN	39.5 (BARG)	366 (°C)			MAX HEAD @ RATED IMPELLER *1.3	
							792 *1.9 (m)	
0	42	MAX	41.3 (BARG)	376 (°C)			MAX POWER @ RATED IMPELLER	
							1900 (kW)	
0	43	ELECTRICITY DRIVERS	HEATING CONTROL				NPSHR AT RATED CAPACITY	
							7.4 (m) (2.1.8)	
0	44	VOLTAGE	6600	240	120	24	SUCTION SPECIFIC SPEED	
							11820 (m ³ /hr - m) (2.1.9)	
0	45	HERTZ	50	50	50		MAX. SOUND PRESS. LEVEL REQ'D	
							<85 (dBA) (2.1.14)	
0	46	PHASE	3	1	1		EST MAX SOUND PRESS. LEVEL	
							84 (dBA) (2.1.14)	



Operational Risk Mitigation

Integrated Repair plan

